



# **20RC**

20RC and 20RCHH are anaerobic resins that are the best method for retaining, locking, and sealing a wide range of metal parts. Even in the tightest fitting assemblies voids are presents which allows for movement and potential loosening of the parts. 20RC and 20RCHH form a tough, durable resin, that fills all these voids, creating a unitized assembly that is completely resistant to shock, vibration, and extremely harsh environmental conditions. These materials cure in the absence of air and in the present of metal. They are ideally suited for retaining cylindrical assemblies providing shock and vibration resistance.

Technology / Base	Methacrylate Ester		
Type of Product	Retaining Compound Adhesive and Sealant		
Components	One Component		
Curing	Anaerobic with Secondary Heat Cure		
Appearance / Color	Green		
Consistency	Viscous Liquid		

### **Features and Benefits**

- Green Anaerobic Retaining Compound and Sealant
- High Strength
- Excellent Gap and Void Filling Capability
- High Resistance to Heat, Corrosion, Vibrations, Water, Gases, Oils, Hydrocarbons, and Many Chemicals

Physical Property	Technical Data Value	Condition/Method
Uncured Material Characteristics	Value	oonanon/wethou
Viscosity	8000 cPs (20RC), 12000 cPs (20RCHV)	Brookfield RVT at 25°C, Spindle 5, 20 rp
Specific Gravity	1.1	Brooklicia KV r at 25 G, Opinaic 5, 20 fp
Flash Point	> 100°C	
Shelf Life	12 months unopened	
	8 to 28°C	
Storage Condition	5 15 =5 5	
Set Time on Steel	12 to 72 hours	
Full Cure Conditions	12 to 72 hours at 25°C	
Cured Material Properties		
Coefficient of Thermal Expansion	80 ppm/K	ASTM D696
Thermal Conductivity	0.1 W/mK	ASTM C177
Specific Heat	0.3 kJ/kgK	
Pin/Collar Shear Strength	>2000 psi	ISO 10123
Service Temperature	-55°C to 150°C	1.00

Cure Speed At Various Temperatures		% of Room Temp	perature Strength
	25%	50%	100%
5°C	28 hrs		
40°C	20 min	40 min	15 to 72 hrs

### Storage

Products should be stored unopened in a cool, dry place out of direct sunlight. Products may be refrigerated for improved shelf life, but should be brought back to room temperature before use.

## Safety and Disposal

For complete safety

### **Curing Performance**

The rate of cure will depend on environmental conditions and the substrates used. The gap of the bond line will affect set speed. Smaller gaps tend to increase set speed. Activators may be applied to further improve set speed, but may also impair overall adhesive performance.





Technica	I D-4-
IACHNICA	ıııata

Cure Speed On Various Substrates		% of Room Temperature Strength	
	25%	50%	100%
Steel	1 hr	1.5 hrs	12 to 72 hrs
Aluminum	6 hrs		
Zn Dichromate	1 hr	1.5 hrs	12 to 72 hrs
Cure Speed For Various Gap Sizes 25%		50%	100%
0.05mm	2 hrs	2.5 hrs	12 to 72 hrs
0.25mm	13 hrs	20 hrs	72 hrs

**Chemical Resistance Testing** 


	T T	0/ -f D T	O = 1!4! =
	Test Temperature	% of Room Temperature Strength	Condition
50% Water/50% Glycol	87°C	80%	1000 hours measured at room conditions
Unleaded Gasoline	22°C	95%	1000 hours measured at room conditions
Motor Oil	125°C	100%	1000 hours measured at room conditions
Brake Fluid	22°C	100%	1000 hours measured at room conditions
Acetone	22°C	95%	1000 hours measured at room conditions
			!

### **General Instructions**

Surfaces to be bonded should be clean and dry and free of grease. Product should be applied in enough quantity to fill all engaged threads or gap. The product performs best in thin bond gaps. Very large gaps may create gaps that will affect the cure speed and overall strength. Good contact is essential. It is recommended to confirm compatibility of the product with all substrates prior to use. This product is not recommended for use with strong oxidizing materials. Where aqueous washing systems are used to clean the surfaces before bonding, these aqueous washes can affect the cure and performance of the adhesive. This product is not normally recommended for use on plastics, users must check compatibility of the product with such substrates.

## **Specifications**

### Hot Strength (%RT strength, tested at temperature)



H.B. Fuller Company 9001 W. Fey Drive Frankfort, IL 60423 +1.800.552.0317

## www.hbfuller.com

# Connecting what matters.™

IMPORTANT: Information, specifications, procedures and recommendations provided ("information") are based on our experience, and we believe this information to be accurate. No representation, guarantee or warranty is made as to the accuracy or completeness of the information or that use of the product will avoid losses or damages or give desired results. It is purchaser's sole responsibility to test and determine the suitability of any product for the intended use. Tests should be repeated if materials or conditions change in any way. No employee, distributor or agent has any right to change these facts and offer a guarantee of performance.

® and ™ are trademarks of H.B. Fuller Company or one of its affiliated entities

H.B. Fuller www.hbfuller.com